PERFECT

Technical specification

		RESULT	ISO PARAMETERS
Description:	Protected leather. Tone-on-tone through from top to bottom European cowhide aniline dyed		
Size:	Full hide (4,90-5,50 SqMt)		
Finishing:	Uniform semi-cover finish		
Thickness:	1.1-1.2 mm		
Light Fastness:	ISO 105-B02	≥8 blue scale	≥5 blue scale
Flex:	ISO 5402	50.000 cycles, No cracks	50.000 cycles, No cracks
Adesion to finish:	ISO 11644	≥2 N/Cm, No cracks	≥2 N/Cm, No cracks
Color Fastness: to rubbing:	ISO 11640/ 11641	500 cycles, ≥5 250 cycles, ≥3/4	500 cycles, ≥5 250 cycles, ≥3/4
Color Fastness to water spotting:	ISO 15700	≥5 grey scale	≥3 grey scale
Cold crack temperature of surface coating:	ISO 17233	-22° no cracks	-15° no cracks
Formaldehyde:	ISO 17226-1	28,5	≤150 ppm
Flammability:	UNI EN 1021-1 (BS 5852 part 1)	Complies	Complies
Country of origin:	Italy		

Cleaning instruction
Perfect is protected from the most common domestic stains, which can be removed by dabbing the leather with a dry cloth, without rubbing. Wash with a damp sponge and a small amount of neutral soap, then pass a sponge dampened with water over the leather and dry with a cloth. Stain removers and detergents sold for treating fabrics must not be used, and it is important that leather articles are not exposed at length to direct sunlight. Slight difference in color between one batch and another are to be considered entirely normal

Rev. 1